



## Home Inspection Report

Prepared exclusively for  
**Mutch Property Group**



PROPERTY INSPECTED:  
**21 Albertus Avenue**  
**Toronto, ON M4R 1J5**

**Date of Inspection: 06/19/2026**

Inspection No. 141168-1977

**COMPANY:**

2295504 Ontario Inc.

A Pillar To Post Authorized Franchise

1485 Gulleden Dr.

Mississauga, ON L4X 2T2

[aaron.palmer@pillartopost.com](mailto:aaron.palmer@pillartopost.com)

(416) 768-9292

**INSPECTOR:**

Aaron Palmer

[aaron.palmer@pillartopost.com](mailto:aaron.palmer@pillartopost.com)

(905) 614-1557

---

*Each office is independently owned and operated*

## REPORT SUMMARY

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the entire report.

### 4.0 ROOFING SYSTEM

#### 4.2 Sloped Surface(s)

4.2.4 Composite tile shingles are premium quality, estimated to be 18 years old, middle of life cycle, and in satisfactory condition.

Typical life expectancy is 40 to 70 years.

4.2.5 Metal flashing/roof is in satisfactory condition. Estimated to be 18 years old.

Typical life expectancy is 40 to 70 years.

#### 4.3 Flat Surface(s)

4.3.2 The flat roof membrane is estimated to be 7 years or less, beginning of life cycle and in satisfactory condition.

Typical life expectancy is 15 - 20 years.

### 7.0 STRUCTURE

#### 7.2 Foundation

7.2.3 Concrete foundation was concealed behind drywall, had normal moisture readings, no signs of seepage, nor efflorescence or water stains, and is in satisfactory condition.

### 9.0 HEATING/COOLING/VENTILATION SYSTEM(S)

#### 9.3 AC / Heat Pump System(s)

9.3.3 Lennox AC unit has 2.0 ton cooling, 7 years old, middle of life cycle, and is in satisfactory condition.

Typical life expectancy is around 15 years.

#### 9.4 Forced Air Furnace(s)

9.4.2 Lennox Hi Eff furnace has 66,000 BTU / Hr Input, is 7 years old, middle of life cycle and was functioning at time of inspection.

Typical life expectancy is around 20 years.

### 10.0 PLUMBING SYSTEM

#### 10.3 Water Main

10.3.2 Estimated 1" Copper supply line to the meter, is located in basement utility room.

\*Main shutoff for all water throughout the home is the flat red handle. Be sure to keep clear access in case of internal water emergencies.

#### 10.6 Water Heating Equipment

10.6.2 Giant Hot Water tank has 60 gallon volume, is 12 years old, has exceeded typical life cycle and was functional at time of inspection.

Typical life expectancy is 10 - 12 years.

While additional years may remain, recommend to budget for replacement.

#### 10.13 Sump Pump

10.13.2 The sump pump is present in the basement at the NW corner and is connected to discharge to the outside. Unit was not tested during the inspection, due to the low water levels.

# INSPECTION REPORT

## 1.0 INTRODUCTION

### 1.1 General Information

1.1.1 A visual maintenance inspection was conducted today. This is not an exhaustive, detailed inspection but rather a general inspection on the key maintenance items; roof, chimney, exterior, windows, landscaping, mechanicals such as hot water tank, furnace and air conditioning. All observations are based on what was visual at the time of inspection. This inspection is not a warranty or guarantee and it should be noted that conditions can quickly change in a short period of time.

No warranty, guarantee or insurance by Pillar to Post is expressed or implied. The report does not include inspection for wood destroying insects, mold, lead or asbestos. A representative sampling of the building components is viewed in areas accessible at the time of inspection. No destructive testing or dismantling of components is performed.

Not all defects will be identified during this inspection. Unexpected repairs should be anticipated.

### 1.2 Scope of Inspection

1.2.1 You are advised to seek 2 professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further, in order to discover and repair related problems that were not identified in the report.

We recommend that all repairs, corrections and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing, including HVAC professionals, electricians, engineers or roofers.

1.2.2 Today's inspection has been conducted in accordance to the CSA Standards of Practice. Please refer to the CSA Standards included in your inspection binder for full Scope and code of ethics.

1.2.3 A visual property inspection is a reasonable effort to disclose the condition of the property on the day and time of the inspection. The inspection is only "visual" and not forensic.

The Home Inspection is NOT a building code compliance inspection.

Various construction codes are revised and changed regularly. Components that require repair or alteration may require replacement and/or upgrading to meet current building, gas or electrical code installation requirements and may have associated costs.

### 1.3 Approximate Year Built

1.3.1 The Home is estimated to be built in: 2007

### 1.4 Inspection / Site Conditions

Sunny

1.4.1 Temperature: 17 degrees

## 2.0 PROPERTY AND SITE

### 2.1 Landscape / Grading

2.1.1 The general landscape such as grading and surface water drainage was inspected.

2.1.2 When trying to minimize basement leakage, it is always best to be proactive and slope grades away from the house. Maintain positive slope away from the house.

2.1.3 Trim and maintain trees, bushes and vines away from the structure to minimize damage/wear to structure and to discourage animal activity.

2.1.4 Best to be proactive and slope grades away from the house. Maintain positive slope away from the house.

### 2.2 Walkway(s)

None - Grass / Stone

Pavers

2.2.1 The walkway(s) were inspected and no significant deficiencies were observed.

### 2.3 Driveway(s)

Pavers

2.3.1 Driveway(s) were inspected.

2.3.2 Some vegetation/weeds growing through the stones and some areas was visible. Recommend a handy person treat/remove to help prevent lifting and separation.

### 3.0 EXTERIOR

#### 3.1 Exterior General Comments

3.1.1 Water can be destructive and foster conditions that can be harmful to health. For this reason, the ideal property will have the ground around the foundation perimeter that slopes away from the residence about 5 inches for the first 10 feet from the foundation. And the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts the discharge and drains or trees that carry or divert water away from the foundation.

Recommend closely monitoring and inspecting the exterior during a heavy rain storm to observe the way the surface water is managed. Standing puddles near the house, or foundation are to be avoided.

We are not exterior experts. Feel free to hire an exterior contractor prior to closing.

3.1.2 The wood fence on the east side is leaning. Recommend a consult the neighbouring property owner to coordinate repair.



#### 3.2 Foundation Surface

- ☑ Concrete
- ☑ Foundation surface is parged (coated with cementitious material).
- ☑ Stucco

3.2.1 The foundation surfaces were inspected and no significant deficiencies were observed, unless otherwise stated.

3.2.2 A crack in the coating is visible along the west side. As this is strictly in the coating, no immediate improvement is required. Ideally, it is recommended to have any crack sealed to help prevent further expansion by a qualified contractor.




### 3.3 Wall Surface

- ☑ Stone Veneer
- ☑ Stucco is the most common surface the area.

3.3.1 The wall surfaces were inspected and no significant deficiencies were observed, unless otherwise stated.

3.3.2 Vines and vegetation may damage the wall surface. Maintain, trim or remove as necessary.



### 3.4 Eaves / Fascia / Soffit

- ☑ Aluminium

3.4.1 The eaves / fascia / soffits were inspected and no significant deficiencies were observed, unless otherwise stated.

### 3.5 Windows

- ☑ Thermal
- ☑ Vinyl

3.5.1 Representative number Inspected

3.5.2 Inspect seal/caulking around window and door frames annually for deterioration. Any cracking or gaps can allow rain (especially if wind-driven) to penetrate through the exterior wall. Repair or re-caulk as required.

### 3.6 Exterior Doors

- Metal



3.6.1 The doors were inspected and no significant deficiencies were observed, unless otherwise stated.

### 3.7 Porch(es)

- Concrete
- Pavers
- Stone

3.7.1 The porch(es) were inspected and no significant deficiencies were observed, unless otherwise stated.

3.7.2 The front porch is functional, showing some gaps in the framing of the wood posts and some deterioration in some of the pavers & mortar. While no immediate improvement is required, recommend a consider a handyman or qualified contractor to repair.



### 3.8 Deck(s)

- Wood

3.8.1 The deck(s) were inspected and no significant deficiencies were observed, unless otherwise stated.


3.8.2 The rear wood deck is functional and in satisfactory condition. Some discolouration is noted, due to the rear end, getting wet and not drying properly because of all the tree foliage. Recommend every year or two to do a power wash to restore the wood to its normal condition.

### 3.9 Basement Walkout

- Concrete

3.9.1 The basement walkout was inspected and no significant deficiencies were observed, unless otherwise stated.

3.9.2 The basement walkout has the required railing, but is missing a drain. Recommend consider installing a drain.



## 4.0 ROOFING SYSTEM

### 4.1 Roofing Inspection Method

- Binoculars / Ground Level
- Drone

4.1.1 Visually Inspected

### 4.2 Sloped Surface(s)

- Metal
- Composite shingles

4.2.1 The sloped surfaces were inspected and no significant deficiencies were observed, unless otherwise stated.

4.2.2 Anticipate that a roofing system exposed to the weather and elements will have to be maintained on an on-going basis in order to continue performing as designed.

As roofing material ages, the probability of weather related damage and leakage increases. Be vigilant for loose shingles, age-related deterioration, and wind and rodent damage. Take note that south or west facing shingles and darker coloured shingles generally have a shorter life expectancy than lighter coloured shingles, and that as shingles age and dry out, roofs are more prone to wind and weather related damage and subsequent leakage. It is recommended a qualified roofer review all roofing components.

4.2.3 We do our best to inspect the roof within the time frame allotted. We inspect the roof covering, drainage systems, the flashing, the chimney, skylights and roof penetrations. We are not required to inspect antennae, interiors of flues or chimneys which are not readily accessible, and other installed accessories. This is not an exhaustive inspection of every installation detail of the roof system according to the manufactures specifications or construction codes.

It is virtually impossible to detect a leak except as it is occurring or by specific water tests, which are beyond our scope of inspection.

We are not professional roofers. Feel free to hire one prior to closing. It is recommended to have a qualified roofer review all components and will provide greater detail and potential warranty on their service, prior to closing.

4.2.4 Composite tile shingles are premium quality, estimated to be 18 years old, middle of life cycle, and in satisfactory condition.

Typical life expectancy is 40 to 70 years.



4.2.5 Metal flashing/roof is in satisfactory condition. Estimated to be 18 years old.

Typical life expectancy is 40 to 70 years.





#### 4.3 Flat Surface(s)





☉ Membrane

4.3.1 The flat surfaces were inspected and no significant deficiencies were observed, unless otherwise stated.

4.3.2 The flat roof membrane is estimated to be 7 years or less, beginning of life cycle and in satisfactory condition.

Typical life expectancy is 15 - 20 years.





#### 4.4 Flashings

- ⊙ Plumbing stack
- ⊙ Skylight
- ⊙ Valley

4.4.1 The flashings were inspected and no significant deficiencies were observed, unless otherwise stated.

#### 4.5 Roof Drainage

- ⊙ Above Ground
- ⊙ Aluminum
- ⊙ Plastic

4.5.1 Roof Drainage Inspected

4.5.2 Some downspouts are discharging too close to the structure. Recommend to extend downspouts to discharge further away and onto a positive slope.

#### 4.6 Skylight(s)

4.6.1 The skylight(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

4.6.2 Monitor skylights frequently for signs of leakage. Skylights are susceptible to water penetration.

### 5.0 ATTIC

#### 5.1 Limitations

- △ No Access

△ Unable to gain access to the attic at the time of inspection.

## 5.2 Attic General Comments

5.2.1 No attic access to inspect structure, components or insulation levels. This is typical with flat roof systems.

## 6.0 GARAGE / CARPORT

### 6.1 Limitations

△ Partially Concealed



△ Storage Items

### 6.2 Garage General Comments

6.2.1 Inspected

6.2.2 Garage General Photos.





### 6.3 Structure

- ☑ Concrete

6.3.1 The structure was inspected and no significant deficiencies were observed, unless otherwise stated.

### 6.4 Interior Access Door(s)

- ☑ Fire rated
- ☑ Self-closing

6.4.1 The interior access door(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

### 6.5 Vehicle Door(s)

- ☑ Automatic
- ☑ Insulated
- ☑ Overhead

6.5.1 The vehicle door(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

### 6.6 Vehicle Door Opener(s)

- ☑ Automatic-belt drive
- ☑ Photo electric sensors

6.6.1 The vehicle door opener(s) were inspected.

6.6.2 Automatic belt drive and eye sensors were functional.

## 6.7 Floor

- ☑ Concrete

6.7.1 The floor was inspected.

## 6.8 Wall

- ☑ Drywall / Plaster

6.8.1 The walls were inspected.

## 6.9 Ceiling

- ☑ Drywall / Plaster

6.9.1 The ceiling was inspected and no significant deficiencies were observed, unless otherwise stated.

## 7.0 STRUCTURE

### 7.1 Limitations

- △ Concealed
- △ Drywall
- △ Finished Basement
- △ Partially Concealed

### 7.2 Foundation

- ☑ Concrete



7.2.1 The foundation was inspected and no significant deficiencies were observed, unless otherwise stated.



7.2.2 Almost every basement leaks under the right conditions. Based on a one time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during the inspection, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters & downspouts, and ground sloping towards the house often cause basement leakage problems.

What to do if your basement leaks:

1. Ensure gutters and downspouts carry roof run-off away from home
2. If problems persist, slope the ground (including walkways, patio and driveways) to direct water away from the home.
3. If the problem is not resolved and the foundation is poured concrete, seal and leaking cracks and form-tie holes from the inside.
4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile (warning high cost).

7.2.3 **Concrete foundation was concealed behind drywall, had normal moisture readings, no signs of seepage, nor efflorescence or water stains, and is in satisfactory condition.**





7.2.4 Finished interior walls were dry at time of inspection when tested with moisture meter.

7.2.5 Foundation is mostly concealed by finished walls preventing full assessment.

### 7.3 Support - Post / Beam / Column

- ☑ Wood beam support

7.3.1 Inspected


7.3.2 A wood beam was partially visible in the utility room.

### 7.4 Floor Structure

- ☑ Engineered wood - TJI

7.4.1 The floor structure was inspected and no significant deficiencies were observed, unless otherwise stated.

7.4.2 Engineered wood floor joists were visible in the basement utility room.



### 7.5 Wall Structure

- ☑ Wood frame

7.5.1 The wall structure was inspected and no significant deficiencies were observed, unless otherwise stated.

## 8.0 ELECTRICAL SYSTEM

## 8.1 Electrical General Comments

8.1.1 If we feel that is safe enough to open the electrical panel, we will check the interior components of service panels and sub panels, the conductors, and overcurrent protection devices. Inside the house, we will check a representative number of installed lighting fixtures, switches and receptacles. This is not an exhaustive inspection of every component and installation detail. There will be receptacles and switches and lights that we will not have time to inspect. Receptacles already in use with plugged in items are not inspected. Receptacles with poor access due to storage items or furniture are not inspected. Therefore it is essential that any recommendations that we make for correction should be completed before closing.

As we are not certified electricians, it is recommended to hire an ESA certified electrician prior to closing. An electrician could reveal other problems or recommend additional repairs upon further investigation.

## 8.2 Service Entrance

8.2.1 Overhead service entrance cables to a meter located outside at SE corner. The majority of the service entrance and metre are concealed by the overgrown vegetation. Recommend to consider trimming back.



## 8.3 Main Disconnect(s)

8.3.1 The main disconnect(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

## 8.4 Distribution Panel(s)

8.4.1 The distribution panel(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

## 8.5 Receptacles

8.5.1 Representative Number Tested

## 8.6 Lighting / Ceiling Fan(s)

8.6.1 A representative number of the lighting / ceiling fan(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

## 8.7 Smoke Alarms

8.7.1 Smoke alarm(s) were present, however were not tested and the functionality was not determined. Consider replacing smoke alarms when taking possession to ensure that new, properly functioning and properly-located fire protection is in place.

## 8.8 Carbon Monoxide Alarms

8.8.1 Carbon monoxide alarm(s) were present, however were not tested and the functionality was not determined. Consider replacing carbon monoxide alarms when taking possession to ensure that new, properly functioning and properly-located fire protection is in place.

## 9.0 HEATING/COOLING/VENTILATION SYSTEM(S)

**9.1 Thermostat(s)**

- Programmable

9.1.1 The thermostat(s) were operated for primary function and worked as intended, unless otherwise stated.

9.1.2 Programmable thermostat is located on the dining room wall.

**9.2 Energy Source(s)**

- Electricity
- Natural Gas

**9.3 AC / Heat Pump System(s)**

- Air Conditioning System
- Central Air Conditioner

9.3.1 AC unit / Heat Pump Inspected


9.3.2 For protection / insurance/ piece of mind, recommend a HIP (Home Insurance program) with the supplier as additional protection. These plans can include annual servicing/ maintenance of furnace, AC and even plumbing.

What Are Protection and Maintenance Plans?

A protection plan is like insurance for your furnace, air conditioner or boiler. The plan covers parts and labour costs for any necessary HVAC equipment repairs.

9.3.3 Lennox AC unit has 2.0 ton cooling, 7 years old, middle of life cycle, and is in satisfactory condition.

Typical life expectancy is around 15 years.



LENNOX		ASSEMBLED IN THE USA	
DALLAS, TEXAS			
M/N XC16S024-230A05			
S/N 5819J12434			
CONTAINS HFC - 410A		DESIGN PRESSURE	
FACTORY CHARGE		HI 448 PSIG	
7 LBS 2 OZS		LO 236 PSIG	
ELECTRICAL RATING		NOMINAL VOLTS 208/230	
1 PH	60 HZ	MIN 197	MAX 253
COMPRESSOR		FAN MOTOR	
PH	1	PH	1
RLA	10.19	FLA	1.0
LRA	55.2	HP	1/6
MIN. CKT. AMPACITY	15.6	MAX FUSE OR CKT. BKR. FUSIBLE COUPE CIRCUIT (RACR PER NEC)	
		20	
5819J12434			
FOR OUTDOOR USE			
AHRI CERTIFIED		ETL US	
Intertek		Intertek	
CONFORMS TO UL STD 1988			
CERTIFIED TO CSA 816 C22.2 NO. 236			
INSTALL PROHIBITED IN PART "A"			

9.3.4 While it was functional, recommend a HVAC technician service the unit annually to maintain performance and prolong service life.


9.4 Forced Air Furnace(s)

- ⦿ High Efficiency

9.4.1 The forced air furnace(s) were operated for primary function and worked as intended.

9.4.2 Lennox Hi Eff furnace has 66,000 BTU / Hr Input, is 7 years old, middle of life cycle and was functioning at time of inspection.

Typical life expectancy is around 20 years.






9.7.2 What yellow handle is the shut off for the natural gas going into the furnace.



9.7.3 The flat yellow handle is the shut off for the natural gas going into the hot water tank.




## 9.8 Filter

- Disposable media
- Electronic air cleaner

9.8.1 The filter(s) were inspected and no significant deficiencies were observed.

9.8.2 An electronic air cleaner is used as well as a disposable filter. The disposable filter size is 16 x 25 x 5. Recommend to change once every 3 months or as per manufacture instructions.



## 10.0 PLUMBING SYSTEM

### 10.1 Limitations

△ The exterior hose bibs could not be operated as they are winterized.

### 10.2 Plumbing General Comments

10.2.1 Most bathroom fixtures, including toilets, tubs, showers, and sinks are inspected. Approximately 5 minutes of water is run at most (if not all) fixtures. Readily visible water supply and drain pipes are inspected. Plumbing access panels that we can find are opened, if readily accessible and available to open. We do not perform water leak tests on drain lines or shower pans. He simply look for active leaks, which is quite limited by our short time in the property.

As we are not professional plumbers, feel free to hire one prior to closing.



### 10.3 Water Main

- ☑ Water main is copper pipe.
- ☑ Main water shut-off valve is in the basement.

10.3.1 Inspected the visible portion of the house water main.

10.3.2 **Estimated 1" Copper supply line to the meter, is located in basement utility room.**

**\*Main shutoff for all water throughout the home is the flat red handle. Be sure to keep clear access in case of internal water emergencies.**



#### 10.4 Distribution Piping

PEX

10.4.1 The visible portions of the water distribution piping was inspected.

10.4.2 The water flow was observed with multiple fixtures operating. Water flow / pressure drop was typical.

10.4.3 Pex piping was visible in utility room.

Waterpex brand was identified.



#### 10.5 Drain, Waste, and Vent Piping

Plastic

10.5.1 The drain, waste and vent piping was inspected and no significant deficiencies were observed.

10.5.2 The visible portions of the interior drain, waste and vent system were inspected.

10.5.3 Black plastic ABS piping was partially visible in the basement utility room.



#### 10.6 Water Heating Equipment

60 gallon

Fuel source is natural gas.


Water heater is located in the basement

10.6.1 The water heating equipment was inspected and no significant deficiencies were observed.

10.6.2 Giant Hot Water tank has 60 gallon volume, is 12 years old, has exceeded typical life cycle and was functional at time of inspection.

Typical life expectancy is 10 - 12 years.

While additional years may remain, recommend to budget for replacement.



10.7 Water Heater Venting

- ☑ Power vented

10.7.1 The combustion and venting of the water heating equipment was inspected.

10.7.2 The water heater venting was inspected and no significant deficiencies were observed.

10.7.3 Power vented to the exterior.



10.8 Hose Bib(s)

10.8.1 The exterior hose bibs were inspected but not operated.

10.8.2 Shut Off not Verified

10.9 Fixtures / Faucets

- ☑ Functional
- ☑ No Leaks Found

10.9.1 Faucets operated.

**10.10 Sink(s)**

- ☑ Functional
- ☑ No Leaks Found

10.10.1 The sinks were operated and functioned as intended.

**10.11 Toilet(s)**

- ☑ Functioning as Intended
- ☑ Secured to Floor

10.11.1 The toilet(s) were operated and functioned as intended.

**10.12 Tub(s) / Shower(s)**

- ☑ Functional
- ☑ No Leaks Found

10.12.1 The tub(s) / shower(s) were operated and functioned as intended.

**10.13 Sump Pump**

- ☑ Discharges to exterior
- ☑ Submersible

10.13.1 Sump pump not operated

10.13.2 **The sump pump is present in the basement at the NW corner and is connected to discharge to the outside. Unit was not tested during the inspection, due to the low water levels.**



10.13.3 A battery backup / high water alarm for the sump pump is not present. Recommend consider installing a battery backup / high water alarm to ensure proper function in the event of a mechanical failure or power outage.

**11.0 INTERIOR****11.1 Floors**

- ☑ Area Rug
- ☑ Ceramic
- ☑ Hardwood

11.1.1 The floors were inspected and no significant deficiencies were observed.

**11.2 Walls / Ceilings**

- ☑ Drywall

11.2.1 The ceilings were inspected and no significant deficiencies were observed.

11.2.2 The walls were inspected and no significant deficiencies were observed.

11.2.3 Imperfections and blemishes noted. Considered to be cosmetic in nature.

**11.3 Windows**

Thermal

Vinyl

11.3.1 Representative number Inspected

11.3.2 Windows appear to be original, 18 years old, thermal, functional, and in satisfactory condition.

**11.4 Doors**

Wood

11.4.1 Representative Number Tested

**11.5 Stairs / Railings / Guardrails**

Wood

11.5.1 The stairs, handrail(s) and guardrail(s) were inspected and no significant deficiencies were observed, unless otherwise stated.

**12.0 FIREPLACE(S)****12.1 Gas Insert(s)**

12.1.1 The gas insert(s) were operated and functioned as intended. Inspection by a fireplace specialist is recommended to evaluate the functionality and safety of the entire system.

12.1.2 Gas fireplaces were present, was operational when tested, however the safety of the unit was not determined. If the smell of gas or irregular function is noticed, recommend a qualified gas heating technician inspect the unit & connections to determine functionality and compliance with modern safety standards.





### 13.0 APPLIANCES

#### 13.1 Refrigerator

Functional

13.1.1 The refrigerator(s) were operated for primary function and worked as intended.

13.1.2 LG refrigerator & freezer were tested and found to be functional.



#### 13.2 Ranges / Ovens / Cooktops

Cooktop

Electric



13.2.1 Not Tested

13.2.2 Oven not tested on a full cycle

13.2.3 The oven(s) were operated for primary function and worked as intended.

13.2.4 LG induction cooktop was present, but unable to test due to being induction (need magnetic pots and pans).

The KitchenAid oven was quick, tested, and the heating feature was functional.



### 13.3 Range Hood

- Vented Outside

13.3.1 The range hood(s) were operated for primary function and worked as intended.

13.3.2 LG Range hood was tested and both fan and light features were functional.



### 13.4 Dishwasher

- ☑ Built-in
- ☑ No Leaks Found

13.4.1 Not Tested

13.4.2 Fisher & Paykel dishwasher was present, responded to operating controls but not tested on a cycle.



### 13.5 Microwave Oven

- ☑ Built-in

13.5.1 The microwave oven(s) were operated for primary function and worked as intended.

13.5.2 Panasonic microwave was tested and found to be functional.



### 13.6 Clothes Dryer

13.6.1 LG combo washer and dryer all in one is present in the top level closet. As tested the unit was functional.



## 14.0 GENERAL COMMENTS ABOUT THIS INSPECTION

### 14.1 Limitations

#### 14.1.1 Conclusion:

We are proud of our service, and trust that you will be happy with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every problem. Also because our inspection essentially visual, latent defects could exist. We cannot see behind walls. Therefore, you should not regard our inspection as a guarantee or warranty. It is simply a report on the general condition of the property at a given point in time. As a homeowner, you should expect problems to occur. Roofs will leak, basements may have water problems, and systems may fail without warning. We cannot predict future events. For these reasons, you should keep a comprehensive insurance policy current.

Thank you for taking the time to read this report, and call us if you have any questions. We are always attempting to improve the quality of our service and our report.